



The following document contains information on Cypress products. Although the document is marked with the name "Spansion" and "Fujitsu", the company that originally developed the specification, Cypress will continue to offer these products to new and existing customers.

Continuity of Specifications

There is no change to this document as a result of offering the device as a Cypress product. Any changes that have been made are the result of normal document improvements and are noted in the document history page, where supported. Future revisions will occur when appropriate, and changes will be noted in a document history page.

Continuity of Ordering Part Numbers

Cypress continues to support existing part numbers. To order these products, please use only the Ordering Part Numbers listed in this document.

For More Information

Please contact your local sales office for additional information about Cypress products and solutions.

About Cypress

Cypress (NASDAQ: CY) delivers high-performance, high-quality solutions at the heart of today's most advanced embedded systems, from automotive, industrial and networking platforms to highly interactive consumer and mobile devices. With a broad, differentiated product portfolio that includes NOR flash memories, F-RAM™ and SRAM, Traveo™ microcontrollers, the industry's only PSoC® programmable system-on-chip solutions, analog and PMIC Power Management ICs, CapSense® capacitive touch-sensing controllers, and Wireless BLE Bluetooth® Low-Energy and USB connectivity solutions, Cypress is committed to providing its customers worldwide with consistent innovation, best-in-class support and exceptional system value.

Errata

This errata sheet is for F²MC-16FX Family Programming Manual Rev. 3 (CM44-00203-3E).

F²MC-16FX
16-BIT MICROCONTROLLER
PROGRAMMING MANUAL

2011.1.17

: Collected Part

Date	Page	Item	Description																				
2011/ 1/17	38	5.1	<p>“• String manipulation instructions” was corrected as corrected by the shading below.</p> <p>(Error)</p> <ul style="list-style-type: none"> • String manipulation instructions <table style="margin-left: 20px; border-collapse: collapse;"> <tr> <td style="padding-right: 10px;">MOVS</td> <td style="padding-right: 10px;">MOVSW</td> <td style="padding-right: 10px;">SCEQ</td> <td>SCWEQ</td> </tr> <tr> <td>FILS</td> <td>FILSW</td> <td></td> <td></td> </tr> </table> <p>(Correct)</p> <ul style="list-style-type: none"> • String manipulation instructions <table style="margin-left: 20px; border-collapse: collapse;"> <tr> <td style="padding-right: 10px;">MOVS</td> <td style="padding-right: 10px;">MOVSD</td> <td style="padding-right: 10px;">MOVSW</td> <td>MOVSWD</td> </tr> <tr> <td>SCEQ</td> <td>SCEQD</td> <td>SCWEQ</td> <td>SCWEQD</td> </tr> <tr> <td>FILS</td> <td>FILSW</td> <td></td> <td></td> </tr> </table> 	MOVS	MOVSW	SCEQ	SCWEQ	FILS	FILSW			MOVS	MOVSD	MOVSW	MOVSWD	SCEQ	SCEQD	SCWEQ	SCWEQD	FILS	FILSW		
MOVS	MOVSW	SCEQ	SCWEQ																				
FILS	FILSW																						
MOVS	MOVSD	MOVSW	MOVSWD																				
SCEQ	SCEQD	SCWEQ	SCWEQD																				
FILS	FILSW																						
2011/ 1/17	40	5.2	<p>“• String manipulation instructions” was corrected as corrected by the shading below.</p> <p>(Error)</p> <ul style="list-style-type: none"> • String instructions <table style="margin-left: 20px; border-collapse: collapse;"> <tr> <td style="padding-right: 10px;">MOVS</td> <td style="padding-right: 10px;">NOVSW</td> <td style="padding-right: 10px;">SCEQ</td> <td>FILS</td> </tr> <tr> <td>FILSW</td> <td></td> <td></td> <td></td> </tr> </table> <p>If an interrupt is requested during execution of a string manipulation instruction attached with a prefix code, the prefix becomes ineffective for the string manipulation instruction after a return is made from the interrupt handling routine, possibly resulting in a malfunction. Do not place the CMR prefix before these string manipulation instructions.</p> <p>(Correct)</p> <ul style="list-style-type: none"> • String manipulation instructions <table style="margin-left: 20px; border-collapse: collapse;"> <tr> <td style="padding-right: 10px;">MOVS</td> <td style="padding-right: 10px;">MOVSD</td> <td style="padding-right: 10px;">MOVSW</td> <td>MOVSWD</td> </tr> <tr> <td>SCEQ</td> <td>SCEQD</td> <td>SCWEQ</td> <td>SCWEQD</td> </tr> <tr> <td>FILS</td> <td>FILSW</td> <td></td> <td></td> </tr> </table> <p>Placing a CMR prefix before the string manipulation instructions listed above is ignored. Counter register RW0 is referred always using actual value of the register bank pointer (RP), regardless of a CMR prefix is specified or not.</p>	MOVS	NOVSW	SCEQ	FILS	FILSW				MOVS	MOVSD	MOVSW	MOVSWD	SCEQ	SCEQD	SCWEQ	SCWEQD	FILS	FILSW		
MOVS	NOVSW	SCEQ	FILS																				
FILSW																							
MOVS	MOVSD	MOVSW	MOVSWD																				
SCEQ	SCEQD	SCWEQ	SCWEQD																				
FILS	FILSW																						
2011/ 1/17	40	5.2	<p>“• Stack manipulation instructions” was added as below.</p> <ul style="list-style-type: none"> • Stack manipulation instructions <table style="margin-left: 20px; border-collapse: collapse;"> <tr> <td style="padding-right: 10px;">LINK</td> <td>UNLINK</td> </tr> </table> <p>Placing a CMR prefix before the stack manipulation instructions listed above is ignored. Frame pointer RW3 is referred always using actual value of the register bank pointer (RP), regardless of a CMR prefix is specified or not.</p>	LINK	UNLINK																		
LINK	UNLINK																						

Date	Page	Item	Description
2011/1/17	41	5.3	<p>“• String manipulation instructions” was corrected as corrected by the shading below.</p> <p>(Error)</p> <ul style="list-style-type: none"> • String instructions SCEQ SCWEQ FILS FILSW <p>(Correct)</p> <ul style="list-style-type: none"> • String manipulation instructions SCEQ SCEQD SCWEQ SCWEQD FILS FILSW
2011/1/17	154	8.42	<p>The following item was added to “FILS, FILSI (Fill String Byte)”.</p> <ul style="list-style-type: none"> ● Malfunction of instruction execution <p>In F²MC-16FX family, this instruction has a malfunction as the following. Refer to customer information "Failure of String Instructions and WBTC/WBTS Instructions (CI-00002-xE)" for details.</p> <p>Condition of malfunction : The following two cases were happened at the same time.</p> <ul style="list-style-type: none"> • Interrupt disabling is performed just before the instruction execution (with in 4 CPU clock cycles). • An interrupt was generated while executing the instruction. <p>Malfunction : The execution of the instruction is terminated without performing data transfer correctly, and then the next instruction is executed.</p> <p>Possible interrupt disable operations :</p> <ul style="list-style-type: none"> • Clear the interrupt source flags of peripheral functions. • Set the interrupt enable/disable bits of peripheral functions. • Set the interrupt level setting value of a peripheral function (ILR/ICR) to the ILM value or higher. [ILR/ICR values \geq ILM value] • Allow the DMA transfer from a peripheral function for which an interrupt setting has been configured. <p>Other interrupt disable operations (not included) :</p> <ul style="list-style-type: none"> • Clear the interrupt enable flag (CCR:I) • Clear the privileged mode flag (CCR:P). • Change the interruption level mask (ILM) value.

Date	Page	Item	Description
2011/1/17	156	8.43	<p>The following item was added to “FILSW, FILSWI (Fill String Word)”.</p> <ul style="list-style-type: none"> ● Malfunction of instruction execution <p>In F²MC-16FX family, this instruction has a malfunction as the following. Refer to customer information "Failure of String Instructions and WBTC/WBTS Instructions (CI-00002-xE)" for details.</p> <p>Condition of malfunction : The following two cases were happened at the same time.</p> <ul style="list-style-type: none"> • Interrupt disabling is performed just before the instruction execution (with in 4 CPU clock cycles). • An interrupt was generated while executing the instruction. <p>Malfunction : The execution of the instruction is terminated without performing data transfer correctly, and then the next instruction is executed.</p> <p>Possible interrupt disable operations :</p> <ul style="list-style-type: none"> • Clear the interrupt source flags of peripheral functions. • Set the interrupt enable/disable bits of peripheral functions. • Set the interrupt level setting value of a peripheral function (ILR/ICR) to the ILM value or higher. [ILR/ICR values \geq ILM value] • Allow the DMA transfer from a peripheral function for which an interrupt setting has been configured. <p>Other interrupt disable operations (not included) :</p> <ul style="list-style-type: none"> • Clear the interrupt enable flag (CCR:I) • Clear the privileged mode flag (CCR:P). • Change the interruption level mask (ILM) value.
2011/1/17	210	8.74	<p>The following item was added to “MOVS, MOVSI (Move String Byte with Increment)”.</p> <ul style="list-style-type: none"> ● Malfunction of instruction execution 1 <p>In F²MC-16FX family, this instruction has a malfunction as the following. Refer to customer information "Failure of String Instructions and WBTC/WBTS Instructions (CI-00002-xE)" for details.</p> <p>Condition of malfunction : The following two cases were happened at the same time.</p> <ul style="list-style-type: none"> • Interrupt disabling is performed just before the instruction execution (with in 4 CPU clock cycles). • An interrupt was generated while executing the instruction. <p>Malfunction : The execution of the instruction is terminated without performing data transfer correctly, and then the next instruction is executed.</p> <p>Possible interrupt disable operations :</p> <ul style="list-style-type: none"> • Clear the interrupt source flags of peripheral functions. • Set the interrupt enable/disable bits of peripheral functions. • Set the interrupt level setting value of a peripheral function (ILR/ICR) to the ILM value or higher. [ILR/ICR values \geq ILM value] • Allow the DMA transfer from a peripheral function for which an interrupt setting has been configured. <p>Other interrupt disable operations (not included) :</p> <ul style="list-style-type: none"> • Clear the interrupt enable flag (CCR:I) • Clear the privileged mode flag (CCR:P). • Change the interruption level mask (ILM) value.

Date	Page	Item	Description
2011/1/17	210	8.74	<p>The following item was added to “MOVSI (Move String Byte with Increment)”.</p> <ul style="list-style-type: none"> ● Malfunction of instruction execution 2 <p>In F²MC-16FX family, this instruction has a malfunction as the following. Refer to customer information "Execution condition limitation of MOVSI/I, MOVSW/I Instructions (CI-00006-xE)" for details.</p> <p>Condition of malfunction : Source and destination areas are overlapping.</p> <ul style="list-style-type: none"> • $AH - AL < RW0$ • $AH < AL$ (only for the case of wrap-around where $AL=FFFF_H$ and $AH=0000_H$) <p>AH or a bank register (ADB,DTB,PCB,SSB,USB) has been changed immediately before the instruction in the method of all the following.</p> <ul style="list-style-type: none"> • A bank register is changed by two or less instructions just before the instruction execution, and then the bank register is used by the instruction. • After AH or a bank register is changed, or simultaneously, RW0 has not been changed.. • After AH or a bank register is changed, RW0 has not been changed. <p>Malfunction : A wrong data transfer is done.</p>
2011/1/17	211	8.75	<p>The following item was added to “MOVSD (Move String Byte with Decrement)”.</p> <ul style="list-style-type: none"> ● Malfunction of instruction execution <p>In F²MC-16FX family, this instruction has a malfunction as the following. Refer to customer information "Failure of String Instructions and WBTC/WBTS Instructions (CI-00002-xE)" for details.</p> <p>Condition of malfunction : The following two cases were happened at the same time.</p> <ul style="list-style-type: none"> • Interrupt disabling is performed just before the instruction execution (with in 4 CPU clock cycles). • An interrupt was generated while executing the instruction. <p>Malfunction : The execution of the instruction is terminated without performing data transfer correctly, and then the next instruction is executed.</p> <p>Possible interrupt disable operations :</p> <ul style="list-style-type: none"> • Clear the interrupt source flags of peripheral functions. • Set the interrupt enable/disable bits of peripheral functions. • Set the interrupt level setting value of a peripheral function (ILR/ICR) to the ILM value or higher. [ILR/ICR values \geq ILM value] • Allow the DMA transfer from a peripheral function for which an interrupt setting has been configured. <p>Other interrupt disable operations (not included) :</p> <ul style="list-style-type: none"> • Clear the interrupt enable flag (CCR:I) • Clear the privileged mode flag (CCR:P). • Change the interruption level mask (ILM) value.

Date	Page	Item	Description
2011/1/17	213	8.76	<p>The following item was added to “MOVSW, MOVSWI (Move String Word with Increment)”.</p> <ul style="list-style-type: none"> ● Malfunction of instruction execution 1 <p>In F²MC-16FX family, this instruction has a malfunction as the following. Refer to customer information "Failure of String Instructions and WBTC/WBTS Instructions (CI-00002-xE)" for details.</p> <p>Condition of malfunction : The following two cases were happened at the same time.</p> <ul style="list-style-type: none"> • Interrupt disabling is performed just before the instruction execution (with in 4 CPU clock cycles). • An interrupt was generated while executing the instruction. <p>Malfunction : The execution of the instruction is terminated without performing data transfer correctly, and then the next instruction is executed.</p> <p>Possible interrupt disable operations :</p> <ul style="list-style-type: none"> • Clear the interrupt source flags of peripheral functions. • Set the interrupt enable/disable bits of peripheral functions. • Set the interrupt level setting value of a peripheral function (ILR/ICR) to the ILM value or higher. [ILR/ICR values ≥ ILM value] • Allow the DMA transfer from a peripheral function for which an interrupt setting has been configured. <p>Other interrupt disable operations (not included) :</p> <ul style="list-style-type: none"> • Clear the interrupt enable flag (CCR:1) • Clear the privileged mode flag (CCR:P). • Change the interruption level mask (ILM) value.
2011/1/17	213	8.76	<p>The following item was added to “MOVSW, MOVSWI (Move String Word with Increment)”.</p> <ul style="list-style-type: none"> ● Malfunction of instruction execution 2 <p>In F²MC-16FX family, this instruction has a malfunction as the following. Refer to customer information "Execution condition limitation of MOVSI, MOVSWI Instructions (CI-00006-xE)" for details.</p> <p>Condition of malfunction : Source and destination areas are overlapping.</p> <ul style="list-style-type: none"> • $AH - AL < 2 \times RW0$ • $AH < AL$ (only for the case of wrap-around where $AL = FFFF_H$ and $AH = 0000_H$) <p>AH or a bank register (ADB,DTB,PCB,SSB,USB) has been changed immediately before the instruction in the method of all the following.</p> <ul style="list-style-type: none"> • A bank register is changed by two or less instructions just before the instruction execution, and the bank register is used by the instruction. • After AH or a bank register is changed, or simultaneously, RW0 has not been changed.. • After AH or a bank register is changed, RW0 has not been changed. <p>Malfunction : A wrong data transfer is done.</p>

Date	Page	Item	Description
2011/1/17	214	8.77	<p>The following item was added to “MOVSWD (Move String Word with Decrement)”.</p> <ul style="list-style-type: none"> ● Malfunction of instruction execution <p>In F²MC-16FX family, this instruction has a malfunction as the following. Refer to customer information "Failure of String Instructions and WBTC/WBTS Instructions (CI-00002-xE)" for details.</p> <p>Condition of malfunction : The following two cases were happened at the same time.</p> <ul style="list-style-type: none"> • Interrupt disabling is performed just before the instruction execution (with in 4 CPU clock cycles). • An interrupt was generated while executing the instruction. <p>Malfunction : The execution of the instruction is terminated without performing data transfer correctly, and then the next instruction is executed.</p> <p>Possible interrupt disable operations :</p> <ul style="list-style-type: none"> • Clear the interrupt source flags of peripheral functions. • Set the interrupt enable/disable bits of peripheral functions. • Set the interrupt level setting value of a peripheral function (ILR/ICR) to the ILM value or higher. [ILR/ICR values \geq ILM value] • Allow the DMA transfer from a peripheral function for which an interrupt setting has been configured. <p>Other interrupt disable operations (not included) :</p> <ul style="list-style-type: none"> • Clear the interrupt enable flag (CCR:I) • Clear the privileged mode flag (CCR:P). • Change the interruption level mask (ILM) value.
2011/1/17	274	8.116	<p>The following item was added to “SCEQ, SCEQI (Scan String Byte until equal with Increment)”.</p> <ul style="list-style-type: none"> ● Malfunction of instruction execution 1 <p>In F²MC-16FX family, this instruction has a malfunction as the following. Refer to customer information "Failure of String Instructions and WBTC/WBTS Instructions (CI-00002-xE)" for details.</p> <p>Condition of malfunction : The following two cases were happened at the same time.</p> <ul style="list-style-type: none"> • Interrupt disabling is performed just before the instruction execution (with in 4 CPU clock cycles). • An interrupt was generated while executing the instruction. <p>Malfunction : The execution of the instruction is terminated without performing data scan correctly, and then the next instruction is executed.</p> <p>Possible interrupt disable operations :</p> <ul style="list-style-type: none"> • Clear the interrupt source flags of peripheral functions. • Set the interrupt enable/disable bits of peripheral functions. • Set the interrupt level setting value of a peripheral function (ILR/ICR) to the ILM value or higher. [ILR/ICR values \geq ILM value] • Allow the DMA transfer from a peripheral function for which an interrupt setting has been configured. <p>Other interrupt disable operations (not included) :</p> <ul style="list-style-type: none"> • Clear the interrupt enable flag (CCR:I) • Clear the privileged mode flag (CCR:P). • Change the interruption level mask (ILM) value.

Date	Page	Item	Description
2011/1/17	274	8.116	<p>The following item was added to “SCEQ, SCEQI (Scan String Byte until equal with Increment)”.</p> <ul style="list-style-type: none"> ● Malfunction of instruction execution 2 <p>In F²MC-16FX family, this instruction has a malfunction as the following. Refer to customer information "Report on wrong execution of scan string instruction SCEQ/SCWEQ at Interrupt (CI07-00003-xE)" for details.</p> <p>Condition of malfunction :</p> <ul style="list-style-type: none"> • An interrupt request was generated during executing the instruction. • The interrupt service was started at the same time when the specified byte data in AL is found in the field of data. <p>Malfunction :</p> <p>Data in AH, RW0 and the N, Z, V, C flags are wrong at the end of the execution of the instruction.</p>
2011/1/17	276	8.117	<p>The following item was added to “SCEQD (Scan String Byte until equal with Decrement)”.</p> <ul style="list-style-type: none"> ● Malfunction of instruction execution <p>In F²MC-16FX family, this instruction has a malfunction as the following. Refer to customer information "Failure of String Instructions and WBTC/WBTS Instructions (CI-00002-xE)" for details.</p> <p>Condition of malfunction :</p> <p>The following two cases were happened at the same time.</p> <ul style="list-style-type: none"> • Interrupt disabling is performed just before the instruction execution (with in 4 CPU clock cycles). • An interrupt was generated while executing the instruction. <p>Malfunction :</p> <p>The execution of the instruction is terminated without performing data scan correctly, and then the next instruction is executed.</p> <p>Possible interrupt disable operations :</p> <ul style="list-style-type: none"> • Clear the interrupt source flags of peripheral functions. • Set the interrupt enable/disable bits of peripheral functions. • Set the interrupt level setting value of a peripheral function (ILR/ICR) to the ILM value or higher. [ILR/ICR values \geq ILM value] • Allow the DMA transfer from a peripheral function for which an interrupt setting has been configured. <p>Other interrupt disable operations (not included) :</p> <ul style="list-style-type: none"> • Clear the interrupt enable flag (CCR:I) • Clear the privileged mode flag (CCR:P). • Change the interruption level mask (ILM) value.

Date	Page	Item	Description
2011/1/17	276	8.117	<p>The following item was added to “SCEQD (Scan String Byte until equal with Decrement)”.</p> <ul style="list-style-type: none"> ● Malfunction of instruction execution 2 <p>In F²MC-16FX family, this instruction has a malfunction as the following. Refer to customer information "Report on wrong execution of scan string instruction SCEQ/SCWEQ at Interrupt (CI07-00003-xE)" for details.</p> <p>Condition of malfunction :</p> <ul style="list-style-type: none"> • An interrupt request was generated during executing the instruction. • The interrupt service was started at the same time when the specified byte data in AL is found in the field of data. <p>Malfunction :</p> <p>Data in AH, RW0 and the N, Z, V, C flags are wrong at the end of the execution of the instruction.</p>
2011/1/17	278	8.118	<p>The following item was added to “SCWEQ, SCWEQI (Scan String Word until equal with Increment)”.</p> <ul style="list-style-type: none"> ● Malfunction of instruction execution 1 <p>In F²MC-16FX family, this instruction has a malfunction as the following. Refer to customer information "Failure of String Instructions and WBTC/WBTS Instructions (CI-00002-xE)" for details.</p> <p>Condition of malfunction :</p> <p>The following two cases were happened at the same time.</p> <ul style="list-style-type: none"> • Interrupt disabling is performed just before the instruction execution (with in 4 CPU clock cycles). • An interrupt was generated while executing the instruction. <p>Malfunction :</p> <p>The execution of the instruction is terminated without performing data scan correctly, and then the next instruction is executed.</p> <p>Possible interrupt disable operations :</p> <ul style="list-style-type: none"> • Clear the interrupt source flags of peripheral functions. • Set the interrupt enable/disable bits of peripheral functions. • Set the interrupt level setting value of a peripheral function (ILR/ICR) to the ILM value or higher. [ILR/ICR values \geq ILM value] • Allow the DMA transfer from a peripheral function for which an interrupt setting has been configured. <p>Other interrupt disable operations (not included) :</p> <ul style="list-style-type: none"> • Clear the interrupt enable flag (CCR:I) • Clear the privileged mode flag (CCR:P). • Change the interruption level mask (ILM) value.

Date	Page	Item	Description
2011/1/17	278	8.118	<p>The following item was added to “SCWEQ, SCWEQI (Scan String Word until equal with Increment)”.</p> <ul style="list-style-type: none"> ● Malfunction of instruction execution 2 <p>In F²MC-16FX family, this instruction has a malfunction as the following. Refer to customer information "Report on wrong execution of scan string instruction SCEQ/SCWEQ at Interrupt (CI07-00003-xE)" for details.</p> <p>Condition of malfunction :</p> <ul style="list-style-type: none"> • An interrupt request was generated during executing the instruction. • The interrupt service was started at the same time when the specified word data in AL is found in the field of data. <p>Malfunction :</p> <p>Data in AH, RW0 and the N, Z, V, C flags are wrong at the end of the execution of the instruction.</p>
2011/1/17	280	8.119	<p>The following item was added to “SCWEQD (Scan String Word until equal with Decrement)”.</p> <ul style="list-style-type: none"> ● Malfunction of instruction execution 1 <p>In F²MC-16FX family, this instruction has a malfunction as the following. Refer to customer information "Failure of String Instructions and WBTC/WBTS Instructions (CI-00002-xE)" for details.</p> <p>Condition of malfunction :</p> <p>The following two cases were happened at the same time.</p> <ul style="list-style-type: none"> • Interrupt disabling is performed just before the instruction execution (with in 4 CPU clock cycles). • An interrupt was generated while executing the instruction. <p>Malfunction :</p> <p>The execution of the instruction is terminated without performing data scan correctly, and then the next instruction is executed.</p> <p>Possible interrupt disable operations :</p> <ul style="list-style-type: none"> • Clear the interrupt source flags of peripheral functions. • Set the interrupt enable/disable bits of peripheral functions. • Set the interrupt level setting value of a peripheral function (ILR/ICR) to the ILM value or higher. [ILR/ICR values \geq ILM value] • Allow the DMA transfer from a peripheral function for which an interrupt setting has been configured. <p>Other interrupt disable operations (not included) :</p> <ul style="list-style-type: none"> • Clear the interrupt enable flag (CCR:I) • Clear the privileged mode flag (CCR:P). • Change the interruption level mask (ILM) value.

Date	Page	Item	Description																												
2011/1/17	280	8.119	<p>The following item was added to “SCWEQD (Scan String Word until equal with Decrement)”.</p> <ul style="list-style-type: none"> ● Malfunction of instruction execution 2 <p>In F²MC-16FX family, this instruction has a malfunction as the following. Refer to customer information "Report on wrong execution of scan string instruction SCEQ/SCWEQ at Interrupt (CI07-00003-xE)" for details.</p> <p>Condition of malfunction :</p> <ul style="list-style-type: none"> • An interrupt request was generated during executing the instruction. • The interrupt service was started at the same time when the specified word data in AL is found in the field of data. <p>Malfunction : Data in AH, RW0 and the N, Z, V, C flags are wrong at the end of the execution of the instruction.</p>																												
2011/1/17	299	8.132	<p>The following item was added to “WBTC (Wait until Bit Condition satisfied)”.</p> <ul style="list-style-type: none"> ● Malfunction of instruction execution <p>In F²MC-16FX family, this instruction has a malfunction as the following. Refer to customer information "Failure of String Instructions and WBTC/WBTS Instructions (CI-00002-xE)" for details.</p> <p>Condition of malfunction : The following two cases were happened at the same time.</p> <ul style="list-style-type: none"> • Interrupt disabling is performed just before the instruction execution (with in 4 CPU clock cycles). • An interrupt was generated while executing the instruction. <p>Malfunction : Bit wait status is cancelled, and then the next instruction is executed.</p> <p>Possible interrupt disable operations :</p> <ul style="list-style-type: none"> • Clear the interrupt source flags of peripheral functions. • Set the interrupt enable/disable bits of peripheral functions. • Set the interrupt level setting value of a peripheral function (ILR/ICR) to the ILM value or higher. [ILR/ICR values \geq ILM value] • Allow the DMA transfer from a peripheral function for which an interrupt setting has been configured. <p>Other interrupt disable operations (not included) :</p> <ul style="list-style-type: none"> • Clear the interrupt enable flag (CCR:1) • Clear the privileged mode flag (CCR:P). • Change the interruption level mask (ILM) value. 																												
2011/1/17	331	APPEN DIX B	<p>Line of RETI instruction of “Table B-12” was corrected as corrected by the shading below.</p> <p>(Error)</p> <table border="1"> <thead> <tr> <th>Mnemonic</th> <th>#</th> <th>~</th> <th></th> <th>Operation</th> <th>LH</th> <th>AH</th> </tr> </thead> <tbody> <tr> <td>RETI</td> <td>1</td> <td>22/6^{*1}</td> <td>1</td> <td>Return from interrupt</td> <td>-</td> <td>-</td> </tr> </tbody> </table> <p>(Correct)</p> <table border="1"> <thead> <tr> <th>Mnemonic</th> <th>#</th> <th>~</th> <th>B</th> <th>Operation</th> <th>LH</th> <th>AH</th> </tr> </thead> <tbody> <tr> <td>RETI</td> <td>1</td> <td>22/6^{*1}</td> <td>1</td> <td>Return from interrupt</td> <td>*</td> <td>*</td> </tr> </tbody> </table>	Mnemonic	#	~		Operation	LH	AH	RETI	1	22/6 ^{*1}	1	Return from interrupt	-	-	Mnemonic	#	~	B	Operation	LH	AH	RETI	1	22/6 ^{*1}	1	Return from interrupt	*	*
Mnemonic	#	~		Operation	LH	AH																									
RETI	1	22/6 ^{*1}	1	Return from interrupt	-	-																									
Mnemonic	#	~	B	Operation	LH	AH																									
RETI	1	22/6 ^{*1}	1	Return from interrupt	*	*																									