



SPANSION LLC  
915 DeGuigne Drive, P.O. Box 3453  
Sunnyvale, California 94088-3453, USA

November 17, 2008

**Obsolescence Notification No:** 2738

**Subject:** Obsolescence of the 110nm, 3.0V MirrorBit® Flash Memory products listed below

Spansion LLC is announcing the discontinuation of the following products. See below for details:

**Product Identification:** S71GL128NB0BFW9Z0  
S71PL127NB0HFW4U0

**Package Types:** TLA064, TSB064

**Product Line:** WSD – Wireless Solutions Division

**Description of Obsolescence:** Obsolescence of the 110nm, 3.0V MirrorBit(R) Flash Memory products listed

**Reason for Obsolescence:** These products are being removed from Spansion's portfolio to consolidate product offerings as a continuous improvement activity.

**Application Impact:** The replacement part for S71GL128NB0BFW9Z0 has no change in footprint but the package dimensions have changed from 8x11.6mm to 8x10mm. Also, please refer to the GL-N to GL-P Migration Guide application note for changes in function. There is no change in fit, form, or function for the S71PL127NB0HFW4U0 replacement..

**Replacement Parts:** S98GL128PB0HW0210  
S71PL127NB0HHW4U0

**Last Order Date:** May 17, 2009

Obsolescence No. 2738  
11/18/08



**Last Shipment Date:** November 17, 2009

**Products Affected By This Obsolescence (part numbers):**

S71GL128NB0BFW9Z0

S71PL127NB0HFW4U0

The date projections above were based on the most current product development status at the time this ACN was issued, but are subject to change. For the latest schedule or additional information, please contact your local sales office or your local distributor.