



February 23, 2012

Obsolescence Notification #: 2845

Obsolescence Title: **Obsolescence of the S29PL127J60TDI130H**

SpanSion LLC is announcing the obsolescence of S29PL127J60TDI130H. See below for details:

Product Identification: S29PL127J60TDI130H

Package Types: TS056

Reason for Obsolescence: This SnBi lead finish Ordering Part Number (OPN) is being removed from SpanSion's product portfolio to promote migration to the next generation Sn lead finish equivalent as a continuous improvement activity.

Application Impact: The OPN S29PL127J60TDI130H will no longer be offered. See below for the recommended replacement OPNs.

Potential Replacement Parts: S29PL127J60TFI130,S29PL127J60TFI130H

Last Order Date: February 23, 2012

Last Shipment Date: February 23, 2012

Products Affected By This Obsolescence (SpanSion part numbers):

S29PL127J60TDI130H

The date projections above were based on the most current product development status at the time this ACN was issued, but are subject to change. For the latest schedule or additional information, please contact your local sales office or your local authorized distributor.

Revision History

The following table shows the revision history for this ACN.

Issue Date	Revision	Description
2/23/2012	None	Initial release

ACN# 2845

Issue Date: February 23, 2012

SpanSion Confidential