

Product Termination Notification (PTN):

Obsolescence of the particular SH-DIP64 and QFP120 products



PTN #: 2880

Issue Date: May 12, 2014

Overview:

SpanSion LLC is announcing the obsolescence of the products which are produced by applying particular Lead-flame. The supply of the Lead-flame terminates along with the Lead-flame business withdrawal of the vendor. Also the equipment for the Lead-flame become too old for manufacturing. Therefore SpanSion LLC has to decide the termination of those products. See below for details:

Product Identification:

Please see attached products list.

Package Types Affected:

SH-DIP64, QFP-120

Description of Obsolescence:

Obsolescence of the products which are produced by applying particular Lead-flame

Reason for Obsolescence:

- The supply of the Lead-flame terminates along with the Lead-flame business withdrawal of the vendor.
- The assembly equipment for the Lead-flame become too old for production

Anticipated Impact:

The ordering part number will no longer be offered.

However we will manufacture necessary stock before production termination as much as possible upon request. If you need production for stock, please let us know the amount of the production until last order date.

Approval of termination: July 18, 2014

Last Order Date: August 20, 2014

Last Shipment Date: March 31, 2015

Products Affected By This Obsolescence:

MB89635P-GT-1156-SH	MB89635P-GT-1346-SH	MB89635P-GT-151-SH
MB89635P-GT-154-SH	MB89635P-GT-158-SH	MB89635P-GT-170-SH
MB89635P-GT-185-SH	MB89635P-GT-215-SH	MB89635P-GT-215-SH
MB89635P-GT-215-SH	MB89635P-GT-218-SH	MB89635P-GT-218-SH
MB89635P-GT-235-SH	MB89635P-GT-236-SH	MB89635P-GT-237-SH
MB89635P-GT-238-SH	MB89635P-GT-261-SH	MB89635P-GT-285-SH
MB89635P-GT-356-SH	MB89635P-GT-356-SH	MB89635P-GT-356-SH
MB89635P-GT-365-SH	MB89635P-GT-365-SH	MB89635P-GT-508-SH
MB89635P-GT-508-SH	MB89637P-GT-1014-SH	MB89637P-GT-1484-SH
MB89637P-GT-194-SH	MB89637P-GT-206-SH	MB89637P-GT-344-SH
MB89637P-GT-419-SH	MB89637P-GT-419-SH	MB89637P-GT-630-SH
MB89637P-GT-655-SH	MB89857P-G-258-SH	MB89857P-G-278-SH
MB89888P-G-125-SHE1	MB89888P-G-134-SHE1	MB89888P-G-135-SHE1
MB89888P-G-136-SHE1	MB89888P-G-147-SH	MB89888P-G-147-SHE1
MB89888P-G-152-SHE1	MB89888P-G-155-SH	MB89888P-G-157-SH
MB89888P-G-158-SH	MB89888P-G-163-SH	MB89888P-G-164-SH
MB89888P-G-166-SH	MB89888P-G-170-SHE1	MB89888P-G-174-SH
MB89888P-G-177-SHE1	MB89888P-G-178-SH	MB89888P-G-179-SH
MB89888P-G-180-SHE1	MB89P625P-G-SH-L	MB89P625P-G-SH-L
MB89P625P-G-SH-L	MB89P625P-G-SH-L	MB89P625P-G-SH-LE1
MB90661AP-G-123-SH	MB89023P-GT-258-SH	MB89023P-GT-270-SH
MB89023P-GT-277-SH	MB89P637P-G-SH	MB89P637P-G-SH
MB89P637P-G-SH	MB89P637P-G-SHE1	MB89P637P-G-SHE1
MB89P637P-G-SHE1	MB89P637P-G-SHE1	MB89P637P-G-SHE1
MB89P637P-G-SHE1	MB89P637P-G-SHE1	MB89P637P-G-SHE1
MB89P637P-G-SHE1	MB89P637P-G-SHE1	MB89P637P-G-SHE1
MB89P637P-GT-5035SH	MB89P637P-GT-5053SH	MB89P637P-GT-5055SH
MB89P637P-GT-5089SH	MB89P637P-GT-5090SH	MB89P637P-GT-5103SH
MB89P147-V2P-G-SHE1	MB89P637-201P-G-SH	MB89P637-201P-G-SH
MB89P637-201P-G-SHE1	MB89P637-201P-GT-5036SH	MB89P637-201P-GT-5036SH
MB89P637-201P-GT-5056SH	MB90F562P-G-SHE1	MB90522BPFV-GS-151-BND
MB90522BPFV-GS-157	MB90522BPFV-GS-168	MB90522BPFV-G-137-BND
MB90522BPFV-G-141-BND	MB90522BPFV-GS-143-BND	MB90522BPFV-GS-174E1
MB90523BPFV-G-159	MB90573PFV-G-252-BND	

Revision History:

The following table shows the revision history for this product termination notification.

Date	Revision	Description
May 12, 2014	None	Initial Release