



Mac OS X Cypress MSC Driver v1.4.1 Release Notes

General Information:

New features in this release are:

1. USB HDD icons for ATA devices.
2. Support for the ISD-300LP.

Operating System Support:

This release of the driver provides support for Mac OS X 10.2 and newer. Mac OS X 10.2.6 is the current release of Mac OS X.

Testing performed on the following significant releases of the OS:

Mac OS X 10.2.6	(build 6L60)
Mac OS X 10.2	(build 6C115)

New Features:

1. USB HDD icons for ATA Devices

Support for standard USB HDD desktop icons were added to the ISDBlockServices object. This change allows the USB HDD desktop icon to appear instead of the generic HDD icon.

2. Additional VID/PID Support.

New VID/PID dictionaries are added to the driver's plist. The new entry requested for this release is:

ISD-300LP	0x04B4/0x6831
-----------	---------------

The Bug Fixes:

1. **Bug Fixed:** None.

Release Version Modifications

- Release 1.4.0 (August 30, 2002)
 - a. Jaguar Support



- b. Two Installers: one for 10.1.x and one for 10.2.
 - c. Workaround for AT2 and CY4611 issue with Jaguar.
 - d. New Multiple LUN support.
 - e. Additional ATA Security Support.
 - f. More VID/PID entries.
- Release 1.3.2 (June 12, 2002)
 - a. Interrupt Pipe support for FX2
 - b. More VID/PID entries.
 - c. Minor bug fixes.
- Release 1.3 (April 11, 2002)
 - a. Support for ATA Disk Security.
 - b. A new post-installation script.
 - c. And more VID/PID entries.
- Release 1.2 (January 20, 2001)
 - a. An architecture change to accomidate additional MSC chip support.
 - b. A messaging mechanism for handling interrupt pipes.
 - c. OpenService support allows User Space applications access to the IOUSBDevice object.
 - d. And more VID/PID entries.
- Release 1.1
 - a. Never released
- Release 1.0: (Oct 5, 2001)
 - a. Initial release of the driver.