



SPANSION LLC
915 DeGuigne Drive, P.O. Box 3453
Sunnyvale, California 94088-3453, USA

December 15, 2009

Obsolescence Notification No: 2780

Subject: Obsolescence of the PL129N, PL256N, and PL512N based Multi-Chip Products

Spansion LLC is announcing the obsolescence of all Multi-Chip Products (MCP) containing 3.0V Page Mode PL129N, PL256N, or PL512N Flash. See below for details:

Product Identification:

<u>Spansion OPNs</u>	<u>Product Type</u>	<u>Package Types</u>
S71PL129N	128 Megabit (8M x 16) CMOS 3.0 Volt-only Simultaneous Read/Write, Page-Mode Flash Memory with pSRAM MCP	64-ball Fine-Pitch BGA (TLA064)
S71PL256N	256 Megabit (16M x 16) CMOS 3.0 Volt-only Simultaneous Read/Write, Page-Mode Flash Memory with pSRAM MCP	84-ball Fine-Pitch BGA (TLA084) 84-ball Fine-Pitch BGA (TSB084)
S70PL512N	Same Die Stack of Two PL256N CMOS 3.0 Volt-only Simultaneous Read/Write, Page-Mode Flash Memory	84-ball Fine-Pitch BGA (TSB084)

Reason for Obsolescence: This device is being removed from Spansion's product portfolio to promote migration to the next generation equivalent as a continuous improvement activity.

Application Impact: All valid combinations of the products affected will no longer be offered. Recommended replacement products are provided in the below table.



Potential Replacement Parts: Please reference the below table for recommended replacements.

Suggested Replacement Products:

Obsoluted Products	Closest Spansion Replacement Product	Marketing Contacts
S71PL129N	S71PL127N	Adam Harbour (PL) (408) 616-3768 Adam.Harbour@spansion.com
S71PL256N	S29GL256P	
S70PL512N	S29GL512P	Ryan Suzuki (GL) (408) 616-8438 Ryan.Suzuki@spansion.com

Old Part Final Order Date: June 30, 2010

Old Part Final Shipment Date: December 31, 2010

Products Affected By This Obsolescence (part numbers):

S70PL512N00BFE533	S70PL512N00HFE533
S70PL512N00HFW533	S71PL129NB0HFW4U0
S71PL129NB0HHW4U0	S71PL129NC0HFW4U0
S71PL129NC0HHW4U0	S71PL256NC0HFW5U0
S71PL256NC0HHW5U0	

The date projections above were based on the most current product development status at the time this ACN was issued, but are subject to change. For the latest schedule or additional information, please contact your local sales office or your local distributor.